Profile/Photo Observation Report



					ROBOTICS	
02259	Weather: Owner: Surveyor:	City of Hobart S. Bucklin		Coding: Pre Clean: PSR:	M-103-127-M-103-128	
	Clean Date:			·	C	
				Not Controlled		
-						
/		Tape/Media	#:			
er System Evalua	ation Survey (S	S Dia/Height:		8"		
tary Sewage Pip	e	Material:		PVC		
		Lining:		None		
		Direction of	Survey:	Downstream		
L27	DS MH:	M-103-128	То	tal Length Surveyed (ft)	206.8	
2.00	O&M Quick:		2200	O&M Rating:	4.00	
2.22	_	ick:	342A	Structural Rating:	40.00	
2.20	_		342B	Overall Rating:	44.00	
i	of Hobart st 38th Avenue art, IN y er System Evalua stary Sewage Pip	7 Owner: 502259 Surveyor: of Hobart Clean Date: st 38th Avenue art, IN y er System Evaluation Survey (Stary Sewage Pipe 127 DS MH: 2.00 O&M Quick: 2.22 Structural Quick:	7 Owner: City of Hobs 502259 Surveyor: S. Bucklin of Hobart Clean Date: 12/19/202 st 38th Avenue art, IN Year Renewa rer System Evaluation Survey (SS Dia/Height: Material: Lining: Direction of DS MH: M-103-128 2.00 O&M Quick: 2.22 Structural Quick:	7 Owner: City of Hobart 502259 Surveyor: S. Bucklin of Hobart Clean Date: 12/19/2024 St 38th Avenue Flow Control: y Tape/Media #: yer System Evaluation Survey (SS Dia/Height: stary Sewage Pipe Material: Lining: Direction of Survey: Direction of Survey: 127 DS MH: M-103-128 To 2.00 O&M Quick: 2200 2.22 Structural Quick: 342A	Owner: City of Hobart Pre Clean: S02259 Surveyor: S. Bucklin PSR: of Hobart Clean Date: 12/19/2024 Shape: St 38th Avenue Flow Control: Not Controlled art, IN Year Renewed: Tape/Media #: er System Evaluation Survey (SS Dia/Height: 8" stary Sewage Pipe Material: PVC Lining: None Direction of Survey: Downstream 127 DS MH: M-103-128 Total Length Surveyed (ft) 2.00 O&M Quick: 2200 O&M Rating: 2.22 Structural Quick: 342A Structural Rating:	

Positio	n Code	Observation	Video (sec)	Grade
103-127				
.0	AMH	Manhole	0	NA
0.	MWL	Miscellaneous Water Level	69	NA
2.8	DAGS(S01)	Deposits Attached Grease	117	M 2
3.8	TF	Tap Factory	141	NA
8.1	DAGS(F01)	Deposits Attached Grease	180	M 2
49.3	TF	Tap Factory	309	NA
57.3	MWLS(S02)	Miscellaneous Water Level Sag	346	S 2
63.8	TF	Tap Factory	376	NA
67.5	MWLS(F02)	Miscellaneous Water Level Sag	402	S 2
68.6	JAM	Joint Angular Medium	445	S 3
81.2	JAM	Joint Angular Medium	548	S 3
81.2	MWLS(S03)	Miscellaneous Water Level Sag	562	S 2
86.7	TF	Tap Factory	596	NA
92.0	TFA	Tap Factory Activity	641	NA
94.1	MWLS(F03)	Miscellaneous Water Level Sag	666	S 2
94.9	JAM	Joint Angular Medium	709	S 3
98.5	MWLS(S04)	Miscellaneous Water Level Sag	735	S 2
107.7	TF	Tap Factory	771	NA
109.9	MWLS(F04)	Miscellaneous Water Level Sag	795	S 2
120.8	MWLS(S05)	Miscellaneous Water Level Sag	832	S 2
123.7	TF	Tap Factory	857	NA
124.9	MWLS(F05)	Miscellaneous Water Level Sag	878	S 2
142.7	TF	Tap Factory	936	NA
176.3	MWLS(S06)	Miscellaneous Water Level Sag	1043	S 2
186.2	JAM	Joint Angular Medium	1140	S 3
205.0	MWLS(F06)	Miscellaneous Water Level Sag	1215	S 2
/206.3	LRD	Line Right Down	1261	M 2
206.8	AMH	Manhole	1322	NA



Code: AMH Description: Manhole


Distance (ft): .0 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-103-127



MWL Code:

Description: **Miscellaneous Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: DAGS


Description: Deposits Attached Grease

Distance (ft): 2.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 11
Clock To: 2

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 3.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: DAGS


Description: **Deposits Attached Grease**

Distance (ft): 8.1 Structural Grade: 0 2 O&M Grade: Clock Start/From: 11 Clock To: 2

1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F01 Within 8" of Joint: YES

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 49.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:


1st Value: 6.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Description: Miscellaneous Water Level Sag


Distance (ft): 57.3
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 63.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

6



Description: Miscellaneous Water Level Sag


Distance (ft): 67.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks:



Code: JAM

Description: Joint Angular Medium

Distance (ft): 68.6
Structural Grade: 3
O&M Grade: 0


Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks:

...



Code: JAM

Description: Joint Angular Medium

Distance (ft): 81.2 Structural Grade: 3 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **MWLS**


Description: **Miscellaneous Water Level Sag**

Distance (ft): 81.2 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000 Continuous Index: S03 Within 8" of Joint: NO



Code: **TF**

Description: Tap Factory

Distance (ft): 86.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: TFA

Description: Tap Factory Activity

Distance (ft): 92.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Miscellaneous Water Level Sag

Distance (ft): 94.1
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: JAM

Description: Joint Angular Medium

Distance (ft): 94.9
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Description: Miscellaneous Water Level Sag

Distance (ft): 98.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S04
Within 8" of Joint: NO

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 107.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2


Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Description: **Miscellaneous Water Level Sag**

109.9 Distance (ft): Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F04 Within 8" of Joint: NO

Remarks:



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 120.8 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S05** Within 8" of Joint: NO

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 123.7 Structural Grade: 0 0 O&M Grade: Clock Start/From: 10

Clock To:

1st Value: 6.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**


Distance (ft): 124.9 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F05 Within 8" of Joint: NO

Remarks:



Code: **TF**

Description: **Tap Factory**

Distance (ft): 142.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 176.3
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: S06
Within 8" of Joint: NO

Remarks:



Code: JAM

Description: Joint Angular Medium

Distance (ft): 186.2
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 205.0
Structural Grade: 2
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F06
Within 8" of Joint: NO

Remarks:

Tuesday, January 14, 2025 15



Code: LRD

Description: Line Right Down

Distance (ft): 206.3
Structural Grade: 0
O&M Grade: 2

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: AMH
Description: Manhole

Distance (ft): 206.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-103-128