

Profile/Photo Observation Report




Date:	12/11/2024	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	235.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-507-035-028
Customer:	City of Hobart	Clean Date:	09/27/2024	Shape:	C

Street:	South Dekalb Street	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Sidewalk	Tape/Media #:	
Purpose:	Sewer System Evaluation Survey (SS	Dia/Height:	10"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Upstream
US MH:	M-507-028	DS MH:	M-507-035
		Total Length Surveyed (ft):	89.3

O&M Index:	1.67	O&M Quick:	2211	O&M Rating:	5.00
Structural Index:	2.21	Structural Quick:	512A	Structural Rating:	31.00
Overall Index:	2.12	Overall Quick:	512B	Overall Rating:	36.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	0	NA
	.0	MWL	Miscellaneous Water Level	64	NA
	16.1	MWLS(S01)	Miscellaneous Water Level Sag	144	S 2
	24.5	MWLS(F01)	Miscellaneous Water Level Sag	181	S 2
	28.8	MWLS(S02)	Miscellaneous Water Level Sag	208	S 2
	38.0	LR	Line Right	253	M 1
	64.8	HSV	Hole Soil Visible	399	S 5
	64.8	TBI	Tap Break-in Intruding	413	M 2
	68.2	MWLS(F02)	Miscellaneous Water Level Sag	444	S 2
	77.6	MWLS(S03)	Miscellaneous Water Level Sag	497	S 2
	88.6	SSS	Surface Damage Surface Spalling	583	S 2
	89.1	TBI	Tap Break-in Intruding	620	M 2
	89.3	MWLS(F03)	Miscellaneous Water Level Sag	651	S 2
	89.3	MSA	Miscellaneous Survey Abandoned	670	NA
M-507-028					



Code: **AMH**
Description: **Manhole**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-507-035**




Code: **MWL**
Description: **Miscellaneous Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **16.1**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index: **S01**
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **24.5**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index: **F01**
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **28.8**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **20.000**
Continuous Index: **S02**
Within 8" of Joint: **NO**
Remarks:




Code: **LR**
Description: **Line Right**

Distance (ft): **38.0**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **HSV**
Description: **Hole Soil Visible**


Distance (ft): **64.8**
Structural Grade: **5**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code:	TBI
Description:	Tap Break-in Intruding
Distance (ft):	64.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	2
Clock To:	
1st Value:	6.000
2nd Value:	2.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	CONSTANTLY DRIPPING WATER.



Code:	MWLS
Description:	Miscellaneous Water Level Sag
Distance (ft):	68.2
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	F02
Within 8" of Joint:	NO
Remarks:	




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **77.6**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index: **S03**
Within 8" of Joint: **NO**
Remarks:




Code: **SSS**
Description: **Surface Damage Surface Spalling**

Distance (ft): **88.6**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **9**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **TBI**
 Description: **Tap Break-in Intruding**

Distance (ft): **89.1**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **10**
 Clock To:
 1st Value: **6.000**
 2nd Value: **5.000**
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks: **Active**



Code: **MWLS**
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **89.3**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index: **F03**
 Within 8" of Joint: **NO**
 Remarks:



Code:	MSA
Description:	Miscellaneous Survey Abandoned
Distance (ft):	89.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	CAMERA CANT MAKE IT PAST PROTRUDING TAP.