
Date:	04/04/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	204.2	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-303-058-059
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	w hansen blvd		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details	:		Direction of Surv	ey: Downstream	
US MH:	M-303-059	DS MH:	M-303-058	Total Length Surveyed (f	:): <b>200.6</b>
0&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	uick: 0000		. 0.00
Overall Index:	0.00	Overall Quick			0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-059



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TFA
Description:	<b>Tap Factory Active</b>
Distance (ft):	75.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:TFADescription:Tap Factory Active

Distance (ft):89Structural Grade:0O&M Grade:0Clock Start/From:9Clock To:11st Value:42nd Value:4Value Percent:4Continuous Index:4Within 8" of Joint:8Remarks:5

89.2 0 9 4.000

1			
3 an	1	P.	

Code:	TFA		
Description:	<b>Tap Factory Active</b>		
Distance (ft):	152.7		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:	3		
Clock To:			
1st Value:	4.000		

2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:



Code:AMHDescription:Manhole

Distance (ft):	200.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-058