## **Profile/Photo Observation Report**



Date: 04/10/2018 Weather: Coding: **PACP 6.0** Pipe Length (ft): 179.9 Owner: NA Pre Clean: **Not Known** P.O.#: P-503-023-022 **Mark Ruby** PSR: Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN W 39TH PL & W 39 Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-503-022 DS MH: M-503-023 Total Length Surveyed (ft): 146.2

2.70 27.00 O&M Index: O&M Quick: O&M Rating: 2.50 3121 5.00 Structural Index: Structural Quick: Structural Rating: 2.67 32.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
503-0	23				
	0	AMH	Manhole	10	NA
	\0	MWL	Water Level	21	NA
	26.6	TFC	Tap Factory Capped	86	NA
	/28.4	TFC	Tap Factory Capped	102	NA
	63.5	TFC	Tap Factory Capped	185	NA
	65.5	TFC	Tap Factory Capped	202	NA
	75.3	MWL	Water Level	233	NA
	77.5	FL	Fracture Longitudinal	250	S 3
	77.8	TF	Tap Factory	263	NA
	85.4	TBI	Tap Break-in Intruding	290	M 2
	104.0	TFC	Tap Factory Capped	340	NA
	112.3	MMC	Material Change	368	NA
	113.3	TFA	Tap Factory Active	382	NA
	116.5	MMC	Material Change	400	NA
	118.7	RFJ	Roots Fine Joint	416	M 1
	122.7	RMJ	Roots Medium Joint	436	M 3
	124.9	RMJ(S01)	Roots Medium Joint	452	M 3
	124.9	CL	Crack Longitudinal	463	S 2
	136.5	TF	Tap Factory	499	NA
	138.7	RML	Roots Medium Lateral	515	M 3
	//138.7	TFD	Tap Factory Defective	526	M 2
	// 143.2	RMJ(F01)	Roots Medium Joint	547	M 3
	145.0	RBJ	Roots Ball Joint	562	M 4
	146.2	MSA	Abandoned Survey	576	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: M-503-022



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: TFC

Description: Tap Factory Capped


Distance (ft): 26.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TFC** 

Description: Tap Factory Capped

Distance (ft): 28.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFC

Description: Tap Factory Capped

4.000

Distance (ft): 63.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: TFC

Description: Tap Factory Capped



Distance (ft): 65.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From: 10

Clock To: 1st Value:

1st Value: 4.000 2nd Value:

Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 75.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO




Code: FL

Description: Fracture Longitudinal

Distance (ft): 77.5
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 77.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TBI

Description: Tap Break-in Intruding

Distance (ft): 85.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 2

Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 104.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC

Description: Material Change

Distance (ft): 112.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: TFA

Description: Tap Factory Active


Distance (ft): 113.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC


Description: Material Change

Distance (ft): 116.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Code: RFJ

Description: Roots Fine Joint


Distance (ft): 118.7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 122.7
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 9
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 124.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 124.9
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 136.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RML

Description: Roots Medium Lateral


Distance (ft): 138.7
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 10

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: **TFD** 

Description: Tap Factory Defective


Distance (ft): 138.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: RFL



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 143.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: RBJ

Description: Roots Ball Joint

Distance (ft): 145.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 80.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 146.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: RMJ