## **Profile/Photo Observation Report**



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 325.3 Owner: NA Pre Clean: **Not Known** P.O.#: **Mark Ruby** PSR: P-503-089-088 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: guyer st Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-503-088 DS MH: M-503-089 Total Length Surveyed (ft): 306.0

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Quick: Overall Rating: Overall Index:

$\overline{}$	Code	Observation	Video (sec)	Grade
03-089				
0.	RMB	Roots Medium Barrel	10	M 4
0.	АМН	Manhole	22	NA
\.0	MWL	Water Level	33	NA
275.0	TFA	Tap Factory Active	595	NA
306.0	AMH	Manhole	669	NA

Code:

Description:



Distance (ft).	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	6
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

RMB

**Roots Medium Barrel** 



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-089



Code: MWL
Description: Water Level


Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent: **10.000** 

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 275.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 306.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-088