Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/08/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	): <b>229.6</b>	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Mark Ruby	PSR:	P-606-060-061
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	ALLEY BETWEEN	N 8TH ST & W 7TH	Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	Flow direction is	marked wrong.			
Location Detai	ls:		Direction of Survey	Downstream	
US MH:	M-606-061	DS MH: N	A-606-060	Total Length Surveyed (ft)	: <b>218.1</b>
O&M Index:	2.02	O&M Quick:	332K	O&M Rating:	131.00
Structural Index:	2.50	Structural Quid	ck: 3121	Structural Rating:	5.00
Overall Index:	2.03	Overall Quick:	342K	Overall Rating:	136.00

Position	Code	Observation	Video (sec)	Grade
061				
0. //	AMH	Manhole	10	NA
\\.0	MWL	Water Level	21	NA
<u>1</u> \ <u>6.3</u>	MMC	Material Change	45	NA
12.3	MMC	Material Change	69	NA
13.8	DAE	Deposits Attached Encrustation	83	M 2
22.0	DAE	Deposits Attached Encrustation	111	M 2
23.3	TF	Tap Factory	125	NA
\ 24.1	DAE(S01)	Deposits Attached Encrustation	139	M 2
41.1	TF	Tap Factory	185	NA
57.9	ID	Infil Dripper	230	M 3
61.6	IW	Infil Weeper	249	M 2
61.6	DAE(F01)	Deposits Attached Encrustation	260	M 2
66.0	MMC	Material Change	281	NA
70.3	MMC	Material Change	301	NA
70.3	CL	Crack Longitudinal	312	S 2
73.8	DAE(S02)	Deposits Attached Encrustation	331	M 2
95.0	TFD	Tap Factory Defective	385	M 2
95.0	RFL	Roots Fine Lateral	396	M 1
101.1	TF	Tap Factory	420	NA

Thursday, November 16, 2023

112.8	DAE(F02)	Deposits Attached Encrustation	456	M 2
114.2	MMC	Material Change	470	NA
118.1	MMC	Material Change	489	NA
129.6	IW(S04)	Infil Weeper	524	M 2
129.6	DAE(S03)	Deposits Attached Encrustation	535	M 2
153.0	ID	Infil Dripper	594	M 3
/154.1	FL	Fracture Longitudinal	608	S 3
/ 158.4	TF	Tap Factory	628	NA
/ 171.3	DAE	Deposits Attached Encrustation	665	M 2
/180.4	TF	Tap Factory	695	NA
//185.0	DAE	Deposits Attached Encrustation	716	M 2
/200.8	RFJ	Roots Fine Joint	760	M 1
/212.9	RMJ	Roots Medium Joint	795	M 3
212.9	DAE	Deposits Attached Encrustation	807	M 2
212.9	IW	Infil Weeper	818	M 2
214.3	TF	Tap Factory	832	NA
216.6	TF	Tap Factory	849	NA
/218.1	IW(F04)	Infil Weeper	864	M 2
//218.1	DAE(F03)	Deposits Attached Encrustation	876	M 2
/ 218.1	MSA	Abandoned Survey	887	NA

M<del>(</del>606<del>)</del>060



Code: Description:	AMH Manhole
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value:	.0 0 0
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	NO M-606-061




Code: MWL Description: Water Level Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 10.000 Continuous Index: Within 8" of Joint: NO Remarks:




ММС
Material Change
6.3
0
0
NO
PVC



Code: Description:	MMC Material Change
Distance (ft):	12.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	VCP



Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	13.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Distance (ft):	22.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




TF Tap Factory
23.3
0
0
2
4.000




Distance (ft):	24.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	41.1 0 0 10 4.000
Remarks:	



Code:	ID
Description:	Infil Dripper
Distance (ft):	57.9
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	IW
Description:	Infil Weeper
Distance (ft):	61.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Distance (ft):	61.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	



Code: Description:	MMC Material Change
Distance (ft):	66.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	PVC



Code: Description:	MMC Material Change
Distance (ft):	70.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	VCP




Code: Description:	CL Crack Longitudinal
Distance (ft):	70.3
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Distance (ft):	73.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	S02
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TFD Tap Factory Defective
Distance (ft):	95.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	RFL



Code:RFLDescription:Roots Fine Lateral

Distance (ft):	95.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	101.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Distance (ft):	112.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	



Code:	MMC
Description:	Material Change

Distance (ft):	114.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	PVC



Code: MMC Description: Material Change

Distance (ft):	118.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	VCP

Code:




Description:	Infil Weeper
Distance (ft):	129.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S04
Within 8" of Joint:	YES
Remarks:	


IW



Distance (ft):	129.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S03
Within 8" of Joint:	YES
Remarks:	




Code:	ID
Description:	Infil Dripper
Distance (ft):	153.0
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:FLDescription:Fracture Longitudinal


Distance (ft): 154.1 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 1 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES Remarks:




Code: Description:	TF Tap Factory
Distance (ft):	158.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Distance (ft):	171.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	180.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Distance (ft):	185.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	RFJ Roots Fine Joint
Distance (ft):	200.8
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:RMJDescription:Roots Medium Joint

Distance (ft):	212.9
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

Code:


Description:



·	•
Distance (ft):	212.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

DAE

**Deposits Attached Encrustation** 




Code:	IW
Description:	Infil Weeper

Distance (ft):	212.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	214.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	216.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	IW Infil Weeper
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	218.1 0 2 8 4 FO4 YES



Distance (ft):	218.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F03
Within 8" of Joint:	YES
Remarks:	



Code:	
Description:	

MSA Abandoned Survey

Distance (ft):	218.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	Debris