Profile/Ph	oto Observatio	n Report				RedZon
Date:	04/19/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 168.5	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Curtis Montgo	mery	PSR:	P-706-044-043
Customer:		Clean Date:	01/01/1900		Shape:	с
Street:	ALLEY BETWEEN	WATER ST & FLEM	I Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Alley		Tape/Media #:			
Purpose:	Maintenance Rel	ated	Dia/Height:		8"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:	blk rocks stuck in	wheels at 72'.				
Location Detai	ls:		Direction of Sur	vey:	Upstream	
US MH:	M-706-043	DS MH:	M-706-044	Total Le	ngth Surveyed (ft):	74.0
0&M Index:	1.67	O&M Quick:	241	12	O&M Rating:	10.00
Structural Index:	2.00	Structural Qu	ick: 220	00	Structural Rating:	4.00
Overall Index:	1.75	Overall Quick	: 261	12	Overall Rating:	14.00

		Position	Code	Observation	Video (sec)	Grade
M	706-04	14				
	\checkmark	.0	AMH	Manhole	10	NA
	L \	.0	MWL	Water Level	20	NA
		4.4	TF	Tap Factory	39	NA
		14.2	RFJ	Roots Fine Joint	69	M 1
		24.4	RFJ	Roots Fine Joint	100	M 1
		32.5	RFB	Roots Fine Barrel	127	M 2
		33.3	TFD	Tap Factory Defective	139	M 2
		44.9	DAZ	Deposits Attached Other	173	M 2
		49.2	CL	Crack Longitudinal	192	S 2
5		49.2	TBI	Tap Break-in Intruding	203	M 2
ecti		50.6	CL	Crack Longitudinal	216	S 2
Camera Direction		72.5	TF	Tap Factory	271	NA
ner		74.0	MSA	Abandoned Survey	284	NA
E.						
Ļ						
м	706-04	13				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-044
Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	NO




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	4.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint

Distance (ft):	14.2
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	RFJ Roots Fine Joint
Distance (ft):	24.4
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:RFBDescription:Roots Fine BarrelDistance (ft):32.5Structural Grade:0O&M Grade:2Clock Start/From:4Clock To:11st Value:1

2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	TFD Tap Factory Defective
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To:	33.3 0 2 9
1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	6.000
Remarks:	DSZ 10% in wye



Code:DAZDescription:Deposits Attached Other

Distance (ft):	44.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	4
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	CL Crack Longitudinal
Description.	
Distance (ft):	49.2
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:TBIDescription:Tap Break-in Intruding

Distance (ft):	49.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	
1st Value:	6.000
2nd Value:	2.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	TBI is active



Code:	CL
Description:	Crack Longitudinal
Distance (ft):	50.6
Structural Grade:	
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	

Continuous Index: Within 8" of Joint:

Remarks:



Code:	TF
Description:	Tap Factory

72.5
0
0
9
6.000



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	74.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris