					ROBOTI
Date:	04/09/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): 226.0	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-707-019-020
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Capitol		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:	Cured in Place	2
Category:	NA				
Comment:	sediment at 195'.	-flow incorrect.			
Location Detai	ls:		Direction of Surv	vey: Downstream	
US MH:	M-707-020	DS MH:	M-707-019	Total Length Surveyed (f	t): 196.4
O&M Index:	1.28	O&M Quick:	312	3 O&M Rating:	23.00
Structural Index	0.00	Structural Qu	uick: 000		. 0.00
Overall Index:	1.28	Overall Quick	. 312		23.00

	Position	Code	Observation	Video (sec)	Grade
1.707	-020				
H	-1.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	\\	RFJ	Roots Fine Joint	38	M 1
	-7\ 22.5	TF	Tap Factory	89	NA
	24.8	TF	Tap Factory	105	NA
	__29.6	RFJ	Roots Fine Joint	126	M 1
	39.6	RFJ(SO1)	Roots Fine Joint	158	M 1
	63.8	RFJ(F01)	Roots Fine Joint	220	M 1
	72.3	TFD	Tap Factory Defective	251	M 2
	72.3	RFL	Roots Fine Lateral	262	M 1
	74.1	TF	Tap Factory	277	NA
	¬_75.8	TFC	Tap Factory Capped	292	NA
		RFJ	Roots Fine Joint	310	M 1
	\\\	TBD	Tap Break-in Defective	340	M 3
	95.3	RFJ	Roots Fine Joint	366	M 1
	121.5	TF	Tap Factory	430	NA
	123.4	TF	Tap Factory	446	NA
	140.5	RFJ(SO2)	Roots Fine Joint	492	M 1
	149.0	RFJ(F02)	Roots Fine Joint	520	M 1
	172.2	RFB	Roots Fine Barrel	578	M 2
	/175.5	TF	Tap Factory	596	NA
	// 177.6	TFD	Tap Factory Defective	612	M 2
	177.6	RFL	Roots Fine Lateral	623	M 1
	178.2	RFJ	Roots Fine Joint	636	M 1
	196.4	MSA	Abandoned Survey	684	NA



Code:AMHDescription:Manhole

.0
0
0
NO
M-707-020

Code:


Description:




Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

MWL


Water Level




Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	3.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	22.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	4
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TF
Description:	Tap Factory
Distance (ft):	24.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	7
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	RFJ Roots Fine Joint
Distance (ft):	29.6
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	39.6
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	



Code: Description:	RFJ Roots Fine Joint
Distance (ft):	63.8
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TFD Tap Factory Defective
Distance (ft):	72.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	4
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	RFL



Code: Description:	RFL Roots Fine Lateral
Distance (ft):	72.3
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	4
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	74.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	8
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	TFC Tap Factory Capped
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	75.8 0 0 12 4.000
Within 8" of Joint: Remarks:	




Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	78.8
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TBD Tap Break-in Defective
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To:	88.0 0 3 2
1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	4.000 Rfl




Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	95.3
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	121.5 0 0 4 4.000
Within 8" of Joint: Remarks:	




Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	123.4 0 0 8 4.000
Within 8" of Joint: Remarks:	




Code: Description:	RFJ Roots Fine Joint
Distance (ft):	140.5
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S02
Within 8" of Joint:	YES
Remarks:	




Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	149.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	




Code: Description:	RFB Roots Fine Barrel
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	172.2 0 2 8 4
Continuous Index: Within 8" of Joint: Remarks:	NO



Code: Description:	TF Tap Factory
Distance (ft):	175.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	4
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	TFD Tap Factory Defective
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	177.6 0 2 7 4.000



Code: Description:	RFL Roots Fine Lateral
Distance (ft):	177.6
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	7
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	RFJ Roots Fine Joint
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	178.2 0 1 7 10
Within 8" of Joint: Remarks:	YES



Code: Description:

Distance (ft):196.4Structural Grade:0O&M Grade:0Clock Start/From:0Clock To:11st Value:42nd Value:4Value Percent:4Continuous Index:NORemarks:Debris

MSA Abandoned Survey

NO

Debris under water