


Profile/Ph	oto Observation	n Report				RedZone
Date:	03/26/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 83.5	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Byrd Fitz	gerald	PSR:	P-809-003-004
Customer:		Clean Date	e: 01/01/19	00	Shape:	с
Street:	GROSBEAK CT		Flow Contr	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Sidewalk		Tape/Medi	a #:		
Purpose:	Maintenance Rela	ated	Dia/Height	:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction o	f Survey:	Downstream	
US MH:	M-809-003	DS MH:	M-809-004	То	otal Length Surveyed (ft)	81.0
0&M Index:	0.00	O&M Quick		0000	O&M Rating:	0.00
tructural Index:	0.00	Structural C	Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00






Code:	АМН
Description:	Manhole
Distance (ft):	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-003




Code: MWL Description: Water Level

.0
0
0
5.000
NO




Code: Description:	TF Tap Factory
Distance (ft):	14.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	27.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Malue Deveste	

Value Percent: Continuous Index: Within 8" of Joint: Remarks:



Code: Description:	TF Tap Factory
Distance (ft):	66.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	81.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-004