Manhole Inspection Report

Date:	**05/11/2018**	Weather:			Coding:	**RZMACP**
MH#:	**M-1004-047**	Owner:	**NA**		Len. Surveyed:	**8.9**
P.O.#:		Surveyor:	**Jen Costello**		Rim to Invert:	**8.4**
Customer:		Cert. #:	**U-907-5518**		Wall Material:	**Concrete (reinforced)**

Street:	**McAfee Dr. 23' South of Cypress Ln.**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**2914498.161**
Location:		GPS Easting:	**2914498.161**
Drain Area:	**Northeast**	GPS Accuracy:	**Sub-Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**0.00**	O&M Quick:	**0000**	O&M Rating:	**0.00**
Structural Index:	**3.00**	Structural Quick:	**3900**	Structural Rating:	**27.00**
Overall Index:	**3.00**	Overall Quick:	**3900**	Overall Rating:	**27.00**

|	Position	Code	Observation	Video (sec)	Grade
M-1004-047					
	.0	MGO	General Observation	10	NA
	.0	SAV	Surface Aggregate Visible	21	S 3
	2.0	MGO	General Observation	39	NA
	8.9	SAV	Surface Aggregate Visible	66	S 3
	8.9	MGO	General Observation	77	NA

Camera Direction

Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access MH**

Code: **SAV**
Description: **Surface Aggregate Visible**

Distance (ft): **.0**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:

Code: **MGO**
Description: **General Observation**

Distance (ft): **2.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **UNDERSIDE OF FRAME**

Code: **SAV**
Description: **Surface Aggregate Visible**

Distance (ft): **8.9**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:

Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**8.9**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**END SURVEY BENCH IS SUBMERGED**