# Manhole Inspection Report

| | | | | | |
|---|---|---|---|---|---|
| Date: | **05/11/2018** | Weather: | | Coding: | **RZMACP** |
| MH#: | **M-1004-061** | Owner: | **NA** | Len. Surveyed: | **9.4** |
| P.O.#: | | Surveyor: | **Jen Costello** | Rim to Invert: | **9.8** |
| Customer: | | Cert. #: | **U-907-5518** | Wall Material: | **Concrete (reinforced)** |

| | | | |
|---|---|---|---|
| Street: | **Hillcrest Ave. 186' South of Barberry** | Project: | **Hobart, IN** |
| City: | **Hobart, IN** | GPS Northing: | **2912848.304** |
| Location: | | GPS Easting: | **2912848.304** |
| Drain Area: | **Northeast** | GPS Accuracy: | **Sub-Meter** |
| Cover Shape: | **Circular** | Evidence of Surcharge: | **No** |
| Cover Size: | **22.5** | Potential for Runoff: | **None** |
| Comments: | | | |

| | | | | | |
|---|---|---|---|---|---|
| O&M Index: | **1.00** | O&M Quick: | **1300** | O&M Rating: | **3.00** |
| Structural Index: | **0.00** | Structural Quick: | **0000** | Structural Rating: | **0.00** |
| Overall Index: | **1.00** | Overall Quick: | **1300** | Overall Rating: | **3.00** |

| Position | Code | Observation | Video (sec) | Grade |
|---|---|---|---|---|
| **M-1004-061** | | | | |
| .0 | MGP | General Photo | 10 | NA |
| .0 | RFJ | Roots Fine Joint | 20 | M 1 |
| 1.4 | MGO | General Observation | 36 | NA |
| 1.7 | RFJ | Roots Fine Joint | 49 | M 1 |
| 7.1 | RFJ | Roots Fine Joint | 71 | M 1 |
| 9.4 | MGO | General Observation | 86 | NA |






Code: **MGP**
Description: **General Photo**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access MH**



| | |
|---|---|
| Code: | **RFJ** |
| Description: | **Roots Fine Joint** |
| Distance (ft): | **.0** |
| Structural Grade: | **0** |
| O&M Grade: | **1** |
| Clock Start/From: | **12** |
| Clock To: | **12** |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | **NO** |
| Remarks: | |



| | |
|---|---|
| Code: | **MGO** |
| Description: | **General Observation** |
| Distance (ft): | **1.4** |
| Structural Grade: | **0** |
| O&M Grade: | **0** |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | **NO** |
| Remarks: | **UNDERSIDE OF FRAME** |



| | |
|---|---|
| Code: | **RFJ** |
| Description: | **Roots Fine Joint** |
| Distance (ft): | **1.7** |
| Structural Grade: | **0** |
| O&M Grade: | **1** |
| Clock Start/From: | **12** |
| Clock To: | **12** |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | **NO** |
| Remarks: | |

| | |
|---|---|
| Code: | **RFJ** |
| Description: | **Roots Fine Joint** |
| Distance (ft): | **7.1** |
| Structural Grade: | **0** |
| O&M Grade: | **1** |
| Clock Start/From: | **12** |
| Clock To: | **12** |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | **NO** |
| Remarks: | |



| | |
|---|---|
| Code: | **MGO** |
| Description: | **General Observation** |
| Distance (ft): | **9.4** |
| Structural Grade: | **0** |
| O&M Grade: | **0** |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Step: | **NO** |
| Remarks: | **END SURVEY** |