Manhole Inspection Report

Date:	**03/27/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-308-031**	Owner:	**NA**	Len. Surveyed:	**11.3**
P.O.#:		Surveyor:	**John Kuglmaier**	Rim to Invert:	**16.3**
Customer:		Cert. #:	**U-1215-07002349**	Wall Material:	**Concrete (reinforced)**

Street:	**On 61st Ave. 401' East of Colorado S**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**0.0**
Location:		GPS Easting:	**0.0**
Drain Area:	**Southwest**	GPS Accuracy:	**Nearest Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**Yes**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**2.00**	O&M Quick:	**2900**	O&M Rating:	**18.00**
Structural Index:	**0.00**	Structural Quick:	**0000**	Structural Rating:	**0.00**
Overall Index:	**2.00**	Overall Quick:	**2900**	Overall Rating:	**18.00**

Position	Code	Observation	Video (sec)	Grade
M-308-031				
.0	MGP	General Photo	10	NA
.0	DAZ	Deposits Attached Other	21	M 2
1.0	MGP	General Photo	37	NA
1.3	IS	Infil Stain	51	NA
9.4	DAZ	Deposits Attached Other	79	M 2
9.8	MGO	General Observation	91	NA



Code: **MGP**
Description: **General Photo**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:

Code:	**DAZ**
Description:	**Deposits Attached Other**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**10.000**
Step:	**NO**
Remarks:	**Mixed materials**

Code:	**MGP**
Description:	**General Photo**
Distance (ft):	**1.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	

Code:	**IS**
Description:	**Infil Stain**
Distance (ft):	**1.3**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	

Code:	**DAZ**
Description:	**Deposits Attached Other**
Distance (ft):	**9.4**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**10.000**
Step:	**NO**
Remarks:	**Mixed materials**

Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**9.8**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**Ins. Comp.**