Manhole Inspection Report

Date:	**05/15/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-504-126**	Owner:	**NA**	Len. Surveyed:	**6.3**
P.O.#:		Surveyor:	**Jen Costello**	Rim to Invert:	**6.8**
Customer:		Cert. #:	**U-907-5518**	Wall Material:	**Brick**

Street:	**42nd Ave. Between Guyer St. and W**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**41.54191971**
Location:		GPS Easting:	**-87.27771759**
Drain Area:	**Northwest**	GPS Accuracy:	**Nearest Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**1.50**	O&M Quick:	**2111**	O&M Rating:	**3.00**
Structural Index:	**4.00**	Structural Quick:	**5131**	Structural Rating:	**8.00**
Overall Index:	**2.75**	Overall Quick:	**5131**	Overall Rating:	**11.00**

Position	Code	Observation	Video (sec)	Grade
M-504-126				
.0	MGO	General Observation	10	NA
.0	RFJ	Roots Fine Joint	21	M 1
4.6	DSGV	Deposits Settled Gravel	42	M 2
6.3	HSV	Hole Soil Visible	57	S 5
6.3	SAP	Surface Aggregate Projecting	68	S 3
6.3	MGO	General Observation	80	NA



Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **ACCESS MH**

Code: **RFJ**
Description: **Roots Fine Joint**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code: **DSGV**
Description: **Deposits Settled Gravel**

Distance (ft): **4.6**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent: **5.000**
Step: **NO**
Remarks:

Code: **HSV**
Description: **Hole Soil Visible**

Distance (ft): **6.3**
Structural Grade: **5**
O&M Grade: **0**
Clock Start/From: **8**
Clock To: **9**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code:	**SAP**
Description:	**Surface Aggregate Projecting**
Distance (ft):	**6.3**
Structural Grade:	**3**
O&M Grade:	**0**
Clock Start/From:	**3**
Clock To:	**9**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**6.3**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**END SURVEY**