Manhole Inspection Report

Date:	**04/28/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-505-090**	Owner:	**NA**	Len. Surveyed:	**7.3**
P.O.#:		Surveyor:	**Jen Costello**	Rim to Invert:	**7.6**
Customer:		Cert. #:	**U-907-5518**	Wall Material:	**Concrete (reinforced)**

Street:	**4th Pl. 358' East of Wabash Pl.**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**2899662.974**
Location:		GPS Easting:	**2899662.974**
Drain Area:	**West**	GPS Accuracy:	**Sub-Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**2.00**	O&M Quick:	**2100**	O&M Rating:	**2.00**
Structural Index:	**2.00**	Structural Quick:	**2100**	Structural Rating:	**2.00**
Overall Index:	**2.00**	Overall Quick:	**2200**	Overall Rating:	**4.00**

Position	Code	Observation	Video (sec)	Grade
M-505-090				
.0	MGO	General Observation	10	NA
.4	FC	Fracture Circumferential	22	S 2
1.8	MGP	General Photo	37	NA
6.3	OBR	Obstacle Rocks	59	M 2
7.3	MGO	General Observation	73	NA





Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **ACCESS MH**



Code:	**FC**
Description:	**Fracture Circumferential**
Distance (ft):	**.4**
Structural Grade:	**2**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	



Code:	**MGP**
Description:	**General Photo**
Distance (ft):	**1.8**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**UNDERSIDE OF FRAME**

Code:	**OBR**
Description:	**Obstacle Rocks**
Distance (ft):	**6.3**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**10.000**
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**7.3**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**END SURVEY**