Manhole Inspection Report

Date:	**04/24/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-506-008**	Owner:	**NA**	Len. Surveyed:	**9.0**
P.O.#:		Surveyor:	**Jen Costello**	Rim to Invert:	**9.6**
Customer:		Cert. #:	**U-907-5518**	Wall Material:	**Concrete (reinforced)**

Street:	**Cardinal Ct. 223' South of 8th St.**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**2900360.489**
Location:		GPS Easting:	**2900360.489**
Drain Area:	**Southwest**	GPS Accuracy:	**Sub-Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**2.00**	O&M Quick:	**2100**	O&M Rating:	**2.00**
Structural Index:	**3.00**	Structural Quick:	**4121**	Structural Rating:	**6.00**
Overall Index:	**2.67**	Overall Quick:	**4122**	Overall Rating:	**8.00**

Position	Code	Observation	Video (sec)	Grade
M-506-008				
.0	MGO	General Observation	10	NA
1.3	SSS	Surface Spalling	24	S 2
1.3	MGO	General Observation	36	NA
3.1	IS	Infil Stain	53	NA
7.8	FM	Fracture Multiple	74	S 4
7.8	DSF	Deposits Settled Fine	86	M 2
9.0	MGO	General Observation	100	NA





Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access MH**

Code:	**SSS**
Description:	**Surface Spalling**
Distance (ft):	**1.3**
Structural Grade:	**2**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**1.3**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**UNDERSIDE OF FRAME**

Code:	**IS**
Description:	**Infil Stain**
Distance (ft):	**3.1**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	

Code:	**FM**
Description:	**Fracture Multiple**
Distance (ft):	**7.8**
Structural Grade:	**4**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**2**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	



Code:	**DSF**
Description:	**Deposits Settled Fine**
Distance (ft):	**7.8**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**5.000**
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**9.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**END SURVEY**