Manhole Inspection Report

Date:	**05/02/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-605-036**	Owner:	**NA**	Len. Surveyed:	**6.7**
P.O.#:		Surveyor:	**Jen Costello**	Rim to Invert:	**7.6**
Customer:		Cert. #:	**U-907-5518**	Wall Material:	**Brick**

Street:	**Pennsylvania St. 284' North of 3rd St**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**41.53316116**
Location:		GPS Easting:	**-87.26685333**
Drain Area:	**West**	GPS Accuracy:	**Nearest Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**22.5**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**2.00**	O&M Quick:	**2100**	O&M Rating:	**2.00**
Structural Index:	**3.00**	Structural Quick:	**3100**	Structural Rating:	**3.00**
Overall Index:	**2.50**	Overall Quick:	**3121**	Overall Rating:	**5.00**

Position	Code	Observation	Video (sec)	Grade
M-605-036				
.0	MGP	General Photo	10	NA
.8	DB	Displaced Brick	24	S 3
1.3	MGO	General Observation	38	NA
5.7	DSGV	Deposits Settled Gravel	60	M 2
6.7	MGO	General Observation	72	NA



Code: **MGP**
Description: **General Photo**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access mh**

Code:	**DB**
Description:	**Displaced Brick**
Distance (ft):	**.8**
Structural Grade:	**3**
O&M Grade:	**0**
Clock Start/From:	**11**
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**1.3**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**underside of frame**

Code:	**DSGV**
Description:	**Deposits Settled Gravel**
Distance (ft):	**5.7**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**5.000**
Step:	**NO**
Remarks:	



Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**6.7**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**end survey**