Manhole Inspection Report

Date:	**10/11/2022**	Weather:		Coding:	**RZMACP**
MH#:	**M-804-052**	Owner:	**NA**	Len. Surveyed:	**9.4**
P.O.#:		Surveyor:	**Jen Costello**	Rim to Invert:	**11.1**
Customer:		Cert. #:	**U-907-5518**	Wall Material:	**Brick**

Street:	**Kelly St. 216' North of Hickey St.**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**2291945.029**
Location:	**Local Rural Streets**	GPS Easting:	**2907736.983**
Drain Area:	**Northeast**	GPS Accuracy:	**Sub-Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**No**
Cover Size:	**24.0**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**0.00**	O&M Quick:	**0000**	O&M Rating:	**0.00**
Structural Index:	**3.00**	Structural Quick:	**3200**	Structural Rating:	**6.00**
Overall Index:	**3.00**	Overall Quick:	**3200**	Overall Rating:	**6.00**

Position	Code	Observation	Video (sec)	Grade
M-804-052				
.0	MGO	General Observation	10	NA
.0	SAV	Surface Aggregate Visible	21	S 3
1.3	MMC	Material Change	35	NA
1.3	MGO	General Observation	48	NA
9.4	SAP	Surface Aggregate Projecting	78	S 3
9.4	MGO	General Observation	88	NA



Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **access mh**

Code: **SAV**
Description: **Surface Aggregate Visible**

Distance (ft): **.0**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:

Code: **MMC**
Description: **Material Change**

Distance (ft): **1.3**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **brick**



Code: **MGO**
Description: **General Observation**

Distance (ft): **1.3**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **underside of frame**

Code:	**SAP**
Description:	**Surface Aggregate Projecting**
Distance (ft):	**9.4**
Structural Grade:	**3**
O&M Grade:	**0**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	

Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**9.4**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**end of survey**