Manhole Inspection Report

Date:	**03/28/2018**	Weather:		Coding:	**RZMACP**
MH#:	**M-903-029**	Owner:	**NA**	Len. Surveyed:	**9.3**
P.O.#:		Surveyor:	**John Kuglmaier**	Rim to Invert:	**11.3**
Customer:		Cert. #:	**U-1215-07002349**	Wall Material:	**Concrete (reinforced)**

Street:	**Rand St. 161' East of Hwy 51.**	Project:	**Hobart, IN**
City:	**Hobart, IN**	GPS Northing:	**0.0**
Location:		GPS Easting:	**0.0**
Drain Area:	**Northeast**	GPS Accuracy:	**Nearest Meter**
Cover Shape:	**Circular**	Evidence of Surcharge:	**Yes**
Cover Size:	**23.0**	Potential for Runoff:	**None**
Comments:			

O&M Index:	**2.00**	O&M Quick:	**2200**	O&M Rating:	**4.00**
Structural Index:	**0.00**	Structural Quick:	**0000**	Structural Rating:	**0.00**
Overall Index:	**2.00**	Overall Quick:	**2200**	Overall Rating:	**4.00**

Position	Code	Observation	Video (sec)	Grade
M-903-029				
.0	MGP	General Photo	10	NA
.8	OBZ	Obstacle Other	23	M 2
2.2	MGP	General Photo	40	NA
2.3	IS	Infil Stain	54	NA
7.4	DAZ	Deposits Attached Other	75	M 2
8.8	MGO	General Observation	89	NA



Code: **MGP**
Description: **General Photo**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:

Code: **OBZ**
Description: **Obstacle Other**

Distance (ft): **.8**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **11**
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Step: **YES**
Remarks: **Metal rod**



Code: **MGP**
Description: **General Photo**

Distance (ft): **2.2**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code: **IS**
Description: **Infil Stain**

Distance (ft): **2.3**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **4**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks:



Code:	**DAZ**
Description:	**Deposits Attached Other**
Distance (ft):	**7.4**
Structural Grade:	**0**
O&M Grade:	**2**
Clock Start/From:	**12**
Clock To:	**12**
1st Value:	
2nd Value:	
Value Percent:	**5.000**
Step:	**NO**
Remarks:	**Mixed materials**

Code:	**MGO**
Description:	**General Observation**
Distance (ft):	**8.8**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	**NO**
Remarks:	**Ins. Comp.**