Profile/Photo Observation Report

RedZone ROBOTICS

Date:	**04/16/2018**	Weather:		Coding:	**PACP 6.0**	
Pipe Length (ft):	**320.0**	Owner:	**NA**	Pre Clean:	**Not Known**	
P.O.#:		Surveyor:	**Selasie Honu**	PSR:	**P-504-126.1-126**	
Customer:		Clean Date:	**01/01/1900**	Shape:	**C**	

Street:	**ALLEY BETWEEN N GUYER ST & N WI**	Flow Control:	**Not Controlled**
City:	**Hobart, IN**	Year Renewed:	
Location:	**Light Highway**	Tape/Media #:	
Purpose:	**Not Known**	Dia/Height:	**10"**
Use:	**Sanitary**	Material:	**CP**
Drain Area:	**NA**	Lining:	
Category:	**NA**		
Comment:			
Location Details:		Direction of Survey:	**Downstream**
US MH:	**M-504-126**	DS MH: **M-504-126.1**	Total Length Surveyed (ft): **4.8**

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.00	Structural Quick:	**3100**	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick:	**3100**	Overall Rating:	3.00

	Position	Code	Observation	Video (sec)	Grade
M-504-126					
	.0	SAP	Surface Aggregate Projecting	10	S 3
	.0	MMC	Material Change	22	NA
	.0	AMH	Manhole	33	NA
	.0	MWL	Water Level	44	NA
	4.8	MSA	Abandoned Survey	65	NA

Camera Direction

M-504-126.1

Code:	**SAP**
Description:	**Surface Aggregate Projecting**
Distance (ft):	**.0**
Structural Grade:	**3**
O&M Grade:	**0**
Clock Start/From:	**7**
Clock To:	**5**
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**M-504-126.1**

Code:	**MMC**
Description:	**Material Change**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**VCP**

Code:	**AMH**
Description:	**Manhole**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**M-504-126**

Code:	**MWL**
Description:	**Water Level**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	**5.000**
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	

Code:	**MSA**
Description:	**Abandoned Survey**
Distance (ft):	**4.8**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**camera stopped**