Profile/Photo Observation Report

Date:	**04/22/2018**	Weather:		Coding:	**PACP 6.0**
Pipe Length (ft):	**262.2**	Owner:	**NA**	Pre Clean:	**No Pre-Cleaning**
P.O.#:		Surveyor:	**Jen Costello**	PSR:	**P-505-068-069**
Customer:		Clean Date:	**01/01/1900**	Shape:	**C**

Street:	**FOXCROFT STREET**	Flow Control:	**Not Controlled**
City:	**Hobart, IN**	Year Renewed:	
Location:	**Light Highway**	Tape/Media #:	
Purpose:	**Routine Assessment**	Dia/Height:	**10"**
Use:	**Sanitary**	Material:	**VCP**
Drain Area:	**NA**	Lining:	
Category:	**NA**		
Comment:	**P_C at 20 ft roots. Flow direction wrong**		
Location Details:		Direction of Survey:	**Downstream**

US MH: **M-505-069** DS MH: **M-505-068** Total Length Surveyed (ft): **21.8**

O&M Index:	**3.00**	O&M Quick:	**3200**	O&M Rating:	**6.00**
Structural Index:	**0.00**	Structural Quick:	**0000**	Structural Rating:	**0.00**
Overall Index:	**3.00**	Overall Quick:	**3200**	Overall Rating:	**6.00**

	Position	Code	Observation	Video (sec)	Grade
M-505-069					
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	22	NA
	17.3	RMJ	Roots Medium Joint	68	M 3
	20.7	RMJ	Roots Medium Joint	87	M 3
	21.8	MSA	Abandoned Survey	101	NA



Code:	**AMH**
Description:	**Manhole**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**M-505-069**

Code:	**MWL**
Description:	**Water Level**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	**20.000**
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	

Code:	**RMJ**
Description:	**Roots Medium Joint**
Distance (ft):	**17.3**
Structural Grade:	**0**
O&M Grade:	**3**
Clock Start/From:	**8**
Clock To:	**9**
1st Value:	
2nd Value:	
Value Percent:	**5.000**
Continuous Index:	
Within 8" of Joint:	**YES**
Remarks:	



Code:	**RMJ**
Description:	**Roots Medium Joint**
Distance (ft):	**20.7**
Structural Grade:	**0**
O&M Grade:	**3**
Clock Start/From:	**7**
Clock To:	**5**
1st Value:	
2nd Value:	
Value Percent:	**30.000**
Continuous Index:	
Within 8" of Joint:	**YES**
Remarks:	



Code:	**MSA**
Description:	**Abandoned Survey**
Distance (ft):	**21.8**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**rmj**