Profile/Photo Observation Report

RedZone ROBOTICS

Date:	**05/06/2018**	Weather:		Coding:	**PACP 6.0**
Pipe Length (ft):		Owner:	**City of Hobart**	Pre Clean:	**No Pre-Cleaning**
P.O.#:	**600**	Surveyor:	**M. Pielacha**	PSR:	**P-905-013-014**
Customer:	**City of Hobart**	Clean Date:		Shape:	**C**

Street:	**Off State Road 130**	Flow Control:	**Not Controlled**	
City:	**Hobart, IN**	Year Renewed:		
Location:	**Other**	Tape/Media #:	**DEP 600**	
Purpose:	**Routine Assessment**	Dia/Height:	**18"**	
Use:	**Sanitary**	Material:	**PVC**	
Drain Area:		Lining:		
Category:	**NA**			
Comment:	**5-21-2018**			
Location Details:		Direction of Survey:	**Upstream**	
US MH:	**M-905-014**	DS MH: **M-905-013**	Total Length Surveyed (ft):	**249.7**

O&M Index:	**0.00**	O&M Quick:	**0000**	O&M Rating:	**0.00**
Structural Index:	**0.00**	Structural Quick:	**0000**	Structural Rating:	**0.00**
Overall Index:	**0.00**	Overall Quick:	**0000**	Overall Rating:	**0.00**

Position	Code	Observation	Video (sec)	Grade

M-905-013

Position	Code	Observation	Video (sec)	Grade
.0	AMH	Manhole	0	NA
.0	MWL	Water Level	13	NA
186.1	TF	Tap Factory	472	NA
249.7	AMH	Manhole	621	NA

Camera Direction

M-905-014

Code:	**AMH**
Description:	**Manhole**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**M-905-013**

Code:	**MWL**
Description:	**Water Level**
Distance (ft):	**.0**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	**15.000**
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	

Code:	**TF**
Description:	**Tap Factory**
Distance (ft):	**186.1**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	**10**
Clock To:	
1st Value:	**4.000**
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	

Code:	**AMH**
Description:	**Manhole**
Distance (ft):	**249.7**
Structural Grade:	**0**
O&M Grade:	**0**
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	**NO**
Remarks:	**M-905-014**