


Manhole Inspection Report



Date:	05/15/2018	Weather:		Coding:	RZMACP
MH#:	M-404-019	Owner:	NA	Len. Surveyed:	2.6
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	3.5
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)

Street:	167' East of Wabash St. 113' North o	Project:	Hobart, IN
City:	Hobart, IN	GPS Northing:	41.54132462
Location:		GPS Easting:	-87.27889252
Drain Area:	Northwest	GPS Accuracy:	Nearest Meter
Cover Shape:	Circular	Evidence of Surcharge:	No
Cover Size:	22.5	Potential for Runoff:	None
Comments:			

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
	M-404-019				
	.0	MGO	General Observation	10	NA
	2.1	DSF	Deposits Settled Fine	26	M 2
	2.6	MGO	General Observation	38	NA



Code: **MGO**
Description: **General Observation**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **ACCESS MH**



Code: **DSF**
Description: **Deposits Settled Fine**

Distance (ft): **2.1**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent: **5.000**
Step: **NO**
Remarks:



Code: **MGO**
Description: **General Observation**

Distance (ft): **2.6**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **END SURVEY**