Manhole Inspection Report



Date: 04/10/2018 Weather:

> M-404-030 Owner:

NA Len. Surveyed: 2.7 John Kuglmaier Surveyor: Rim to Invert:

U-1215-07002349 Concrete Customer: Cert. #: Wall Material:

(reinforced)

RZMACP

3.7

Coding:

Street: City:

Location:

MH#:

P.O.#:

Clark St. 683' North of Ridge Rd.

Project: Hobart, IN **GPS Northing:** 2898379.317

Hobart, IN GPS Easting: 2898379.317

Drain Area: Northwest GPS Accuracy: **Sub-Meter**

Cover Shape: Circular Evidence of Surcharge: Yes Cover Size: 23.0 Potential for Runoff: None


Comments:

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023 1

Position	Code	Observation	Video (sec)	Grade
n- 4 04-030				
.0	MGP	General Photo	10	NA
.5	MGO	General Observation	23	NA
1.1	MGP	General Photo	37	NA
2.3	MGO	General Observation	53	NA
Camera Direction				


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2



MGO Code:

Description: **General Observation**

Distance (ft): .5 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Surcharge



Code: MGP

Description: **General Photo**

Distance (ft): 1.1 Structural Grade: 0 0 O&M Grade: Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent:


NO Step:

Remarks:

Code:

Description: **General Observation**

MGO



Distance (ft): 2.3 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3