Manhole Inspection Report



 Date:
 04/20/2018
 Weather:
 Coding:
 RZMACP

 MH#:
 M-405-045
 Owner:
 NA
 Len. Surveyed:
 15.0

P.O.#: Surveyor: Jen Costello Rim to Invert: 17.9
Customer: Cert. #: U-907-5518 Wall Material: Brick

Street: 3rd St. 120' East of Crestwood Dr. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0
Location: GPS Easting: 0.0

Drain Area: West GPS Accuracy: Nearest Meter


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
И- 4 05- 0 45	5				
	.0	MGO	General Observation	11	NA
-11	1.6	MGP	General Photo	27	NA
	15.0	MGO	General Observation	68	NA
Camera Direction					




Description: **General Observation** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks: **ACCESS MH**

MGO

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 1.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 15.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY