Date:	04/09/2018	Weather:		Coding:	RZMACP
MH#:	M-503-045	Owner:	NA	Len. Surveyed:	6.7
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	8.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	289' East of Virginia St. 172' South o Project:		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing: 2901599.068		
Location:	Northwest Circular		GPS Easting:	2901599.068 Sub-Meter No	
Drain Area:			GPS Accuracy:		
Cover Shape:			Evidence of Surcharge:		
Cover Size: Comments:	23.0	F	Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quic	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

ſ	Position	Code	Observation	Video (sec)	Grade
1-503-045					
	D	MGP	General Photo	10	NA
2	.1	MGP	General Photo	28	NA
4	.6	DSF	Deposits Settled Fine	47	M 2
/[5	.8	MGO	General Observation	61	NA
Π					



Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGPDescription:General Photo

Distance (ft):	2.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	4.6 0 2 12 12 5.000
Step: Remarks:	NO



Code:	MGO
Description:	General Observation
Distance (ft):	5.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.