Manhole Inspection Report



Date:

05/16/2018

Weather:

NA

Coding:

RZMACP

MH#: P.O.#: M-504-061

Owner:

Jen Costello

Rim to Invert:

Len. Surveyed: 13.6 14.5

Customer:

Surveyor: Cert. #:

U-907-5518

Wall Material:

Concrete (reinforced)

Street: City:

Ridge Rd. 31' West of California St.

Project:

Hobart, IN 41.53969955

Location:

GPS Northing: GPS Easting:

-87.27073669

Drain Area:

Cover Shape:

Northwest

Hobart, IN

GPS Accuracy:

Nearest Meter

None

Cover Size:

Circular

22.5

Evidence of Surcharge: No

Comments:

Potential for Runoff:

Overall Quick:

O&M Index:
Structural Index:

Overall Index:

2.00 O&M Quick: 0.00 Structural Quick:

2.00

2200 O&M Rating: 0000 Structural Rating: 2200 Overall Rating:

4.00 0.00 4.00

Positio	n Code	Observation	Video (sec)	Grade
M-504-061				
.0	MGO	General Observation	10	NA
11.8	IW	Infil Weeper	45	M 2
13.6	DSF	Deposits Settled Fine	60	M 2
13.6	MGO	General Observation	71	NA
Camera Direction				

Code:

Description:



Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

MGO

General Observation

Step: NO

Value Percent:

Remarks: ACCESS MH



Code: IW

Description: Infil Weeper

Distance (ft): 11.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 13.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 10

1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 13.6

Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

3

Wednesday, May 3, 2023