Manhole Inspection Report



4.00

Date: 04/26/2018

Owner: NA

Weather:

Coding:

RZMACP

MH#:

M-507-034

Len. Surveyed: Rim to Invert:

P.O.#:

Surveyor: Jen Costello U-907-5518 Cert. #:

Wall Material:

Concrete (reinforced)

5.3

Street: City:

Customer:

West of Dekalb St. 290' South of 10t Project:

GPS Northing:

Hobart, IN 2900308.223

Location:

2900308.223

GPS Easting:

2200

Drain Area: Cover Shape: Southwest Circular

Hobart, IN

GPS Accuracy: **Sub-Meter** Evidence of Surcharge:

No

Cover Size:

22.5

Potential for Runoff:

None

Comments:

O&M Index: Structural Index:

Overall Index:

0.00 2.00

2.00 O&M Quick:

Structural Quick: Overall Quick:

2200 O&M Rating: 0000 Structural Rating:

0.00 4.00 Overall Rating:

	Code	Observation	Video (sec)	Grade
M-507-034				
.0	MGO	General Observation	10	NA
1.4	MGO	General Observation	26	NA
1.9	IW	Infil Weeper	40	M 2
4.3	DSZ	Deposits Settled Other	57	M 2
5.3	MGO	General Observation	70	NA
Camera Direction				



Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

MGO

General Observation


Step: NO

Value Percent:

Remarks: ACCESS MH

Code:

Description:



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 4.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000
Step: NO
Remarks: MISC

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 5.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY