

# Manhole Inspection Report



Date:	<b>04/08/2018</b>	Weather:		Coding:	<b>RZMACP</b>
MH#:	<b>M-603-037</b>	Owner:	<b>NA</b>	Len. Surveyed:	<b>3.2</b>
P.O.#:		Surveyor:	<b>John Kuglmaier</b>	Rim to Invert:	<b>4.5</b>
Customer:		Cert. #:	<b>U-1215-07002349</b>	Wall Material:	<b>Concrete (reinforced)</b>

Street:	<b>Wisconsin St. 219' South of Hwy 6.</b>	Project:	<b>Hobart, IN</b>
City:	<b>Hobart, IN</b>	GPS Northing:	<b>2901790.682</b>
Location:		GPS Easting:	<b>2901790.682</b>
Drain Area:	<b>Northwest</b>	GPS Accuracy:	<b>Sub-Meter</b>
Cover Shape:	<b>Circular</b>	Evidence of Surcharge:	<b>Yes</b>
Cover Size:	<b>23.0</b>	Potential for Runoff:	<b>None</b>
Comments:			

O&M Index:	<b>1.00</b>	O&M Quick:	<b>1100</b>	O&M Rating:	<b>1.00</b>
Structural Index:	<b>0.00</b>	Structural Quick:	<b>0000</b>	Structural Rating:	<b>0.00</b>
Overall Index:	<b>1.00</b>	Overall Quick:	<b>1100</b>	Overall Rating:	<b>1.00</b>

The diagram illustrates a vertical pole with a base and a camera direction indicated by a red arrow pointing downwards. Five observation points are marked on the pole with horizontal lines extending to a table. The points are labeled with their positions: .0, .0, 1.2, 2.1, and 2.7. The table provides details for each point, including the code, observation description, video duration in seconds, and the grade.


Position	Code	Observation	Video (sec)	Grade
.0	MGP	General Photo	10	NA
.0	RFJ	Roots Fine Joint	22	M 1
1.2	MGP	General Photo	38	NA
2.1	MGO	General Observation	53	NA
2.7	MGO	General Observation	66	NA

Code:	<b>MGP</b>
Description:	<b>General Photo</b>



Code: **RFJ**  
Description: **Roots Fine Joint**  
  
Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **2**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---



Code: **MGP**  
Description: **General Photo**  
  
Distance (ft): **1.2**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---



Code: **MGO**  
Description: **General Observation**  
  
Distance (ft): **2.1**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks: **Surcharge**



Code:	<b>MGO</b>
Description:	<b>General Observation</b>
Distance (ft):	<b>2.7</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	<b>NO</b>
Remarks:	<b>Ins. Comp.</b>