
Date:	05/13/2018	Weather:		Coding:	RZMACP
MH#:	M-604-021	Owner:	NA	Len. Surveyed:	11.8
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	13.2
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Intersection of Rid	ge Rd. and Washi	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2902120.238	
Location:			GPS Easting:	2902120.238	
Drain Area:	Northwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qu	ick: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	c 3121	Overall Rating:	5.00

I	Position	Code	Observation	Video (sec)	Grade
-604-021					
	0	MGP	General Photo	10	NA
1	7	MGO	General Observation	27	NA
/1	0.4	SAV	Surface Aggregate Visible	58	S 3
/ [1	0.9	OBR	Obstacle Rocks	72	M 2
+++'					
H					
	_				



MGP	
General Photo	
•	
.0	
0	
0	
NO	
ACCESS MH	



Code:	MGO
Description:	General Observation
	4 7
Distance (ft):	1.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME

SAV

Surface Aggregate Visible



Code:	
Description:	

Distance (ft):	10.4
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	OBR Obstacle Rocks
Distance (ft):	10.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	