Date:	05/14/2018	Weather:		Coding:	RZMACP
MH#:	M-604-099	Owner:	NA	Len. Surveyed:	10.0
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	10.4
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	164' East of Wisconsin St. 398' North Project:			Hobart, IN	
City:	Hobart, IN		GPS Northing:	2901969.062	
Location:			GPS Easting:	2901969.062	
Drain Area:	Northwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qui	ick: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	.: 3121	Overall Rating:	5.00

	Code	Observation	Video (sec)	Grade
504-099				
.0	MGP	General Photo	10	NA
.0	DB	Displaced Brick	21	S 3
1.8	MGO	General Observation	38	NA
4.5	RFB	Roots Fine Barrel	57	M 2
10.0	MGO	General Observation	80	NA



Code:	MGP
Description:	General Photo
	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code: DB Description: **Displaced Brick** Distance (ft): .0 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 12 Clock To: 12 1st Value: 2nd Value: Value Percent: Step: NO Remarks:



Code:	MGO
Description:	General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	1.8 0 0 VNO



Code: Description:	RFB Roots Fine Barrel
Distance (ft):	4.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	10
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft):	10.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY