


Manhole Inspection Report



| | | | | | |
|-----------|-------------------|-----------|---------------------|----------------|---------------|
| Date: | 05/02/2018 | Weather: | | Coding: | RZMACP |
| MH#: | M-605-030 | Owner: | NA | Len. Surveyed: | 7.5 |
| P.O.#: | | Surveyor: | Jen Costello | Rim to Invert: | 8.3 |
| Customer: | | Cert. #: | U-907-5518 | Wall Material: | Brick |

| | | | |
|--------------|--|------------------------|----------------------|
| Street: | Connecticut St. 228' North of 3rd St. | Project: | Hobart, IN |
| City: | Hobart, IN | GPS Northing: | 41.53313446 |
| Location: | | GPS Easting: | -87.26560211 |
| Drain Area: | West | GPS Accuracy: | Nearest Meter |
| Cover Shape: | Circular | Evidence of Surcharge: | No |
| Cover Size: | 22.5 | Potential for Runoff: | None |
| Comments: | | | |


| | | | | | |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index: | 2.00 | O&M Quick: | 2100 | O&M Rating: | 2.00 |
| Structural Index: | 0.00 | Structural Quick: | 0000 | Structural Rating: | 0.00 |
| Overall Index: | 2.00 | Overall Quick: | 2100 | Overall Rating: | 2.00 |

| | Position | Code | Observation | Video (sec) | Grade |
|--|----------|------|-------------------------|-------------|-------|
|  | | | | | |
| | .0 | MGP | General Photo | 10 | NA |
| | 1.5 | MGO | General Observation | 26 | NA |
| | 5.5 | DSGV | Deposits Settled Gravel | 47 | M 2 |
| | 7.5 | MGO | General Observation | 63 | NA |



Code: **MGP**
Description: **General Photo**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **ACCESS MH**



Code: **MGO**
Description: **General Observation**

Distance (ft): **1.5**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **UNDERSIDE OF FRAME**



Code: **DSGV**
Description: **Deposits Settled Gravel**

Distance (ft): **5.5**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent: **5.000**
Step: **NO**
Remarks:



Code: **MGO**
Description: **General Observation**

Distance (ft): **7.5**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: **NO**
Remarks: **END SURVEY**