
Date:	04/27/2018	Weather:		Coding:	RZMACP
MH#:	M-606-023	Owner:	NA	Len. Surveyed:	10.7
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	11.5
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Intersection of Ash St. and 8th St.		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2903196.574	
ocation:		GPS Easting: 2903196.574	2903196.574		
Drain Area:			GPS Accuracy: Evidence of Surcharge:	Sub-Meter	
Cover Shape:				No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	iick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	c: 2100	Overall Rating:	2.00





Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code: Description:	MGP General Photo
Distance (ft):	1.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code: Description:	IW Infil Weeper
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	4.4 0 2 12 12 NO



Code:	MGO
Description:	General Observation
Distance (ft):	10.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY