Manhole Inspection Report



Date: 04/06/2018 Weather: Coding: RZMACP

 MH#:
 M-607-080
 Owner:
 NA
 Len. Surveyed:
 9.5

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 10.2

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Ash St. 1215' South of 10th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

| O&M Index: | 2.00 | O&M Quick: | 2100 | O&M Rating: | 2.00 |
|-------------------|------|-------------------|------|--------------------|------|
| Structural Index: | 0.00 | Structural Quick: | 0000 | Structural Rating: | 0.00 |
| Overall Index: | 2.00 | Overall Quick: | 2100 | Overall Rating: | 2.00 |

Wednesday, May 3, 2023

| Position | Code | Observation | Video (sec) | Grade |
|------------------|------|-----------------------|-------------|-------|
| M-607-080 | | | | |
| .0 | MGP | General Photo | 10 | NA |
| 2.0 | MGP | General Photo | 28 | NA |
| 6.2 | DSF | Deposits Settled Fine | 50 | M 2 |
| 7.7 | MGO | General Observation | 64 | NA |
| | | | | |
| | | | | |
| | | | | |
| Camera Direction | | | | |
| Direc | | | | |
| e | | | | |
| Cam | | | | |
| | | | | |
| * | | | | |
| 111 | | | | |
| H. | | | | |
| - 11 | | | | |
| - 11 | | | | |
| III. | | | | |
| | | | | |
| | | | | |


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 7.7

Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: Step: **NO**

Remarks: Ins. Comp.

Wednesday, May 3, 2023