

# Manhole Inspection Report



Date:	<b>04/17/2018</b>	Weather:		Coding:	<b>RZMACP</b>
MH#:	<b>M-707-038</b>	Owner:	<b>NA</b>	Len. Surveyed:	<b>7.7</b>
P.O.#:		Surveyor:	<b>John Kuglmaier</b>	Rim to Invert:	<b>7.8</b>
Customer:		Cert. #:	<b>U-1215-07002349</b>	Wall Material:	<b>Concrete (reinforced)</b>

Street:	<b>State St. 362' North of 12th St.</b>	Project:	<b>Hobart, IN</b>
City:	<b>Hobart, IN</b>	GPS Northing:	<b>2906210.24</b>
Location:		GPS Easting:	<b>2906210.24</b>
Drain Area:	<b>Southeast</b>	GPS Accuracy:	<b>Sub-Meter</b>
Cover Shape:	<b>Circular</b>	Evidence of Surcharge:	<b>No</b>
Cover Size:	<b>22.5</b>	Potential for Runoff:	<b>None</b>
Comments:			

O&M Index:	<u>2.00</u>	O&M Quick:	<u>2100</u>	O&M Rating:	<u>2.00</u>
Structural Index:	<u>0.00</u>	Structural Quick:	<u>0000</u>	Structural Rating:	<u>0.00</u>
Overall Index:	<u>2.00</u>	Overall Quick:	<u>2100</u>	Overall Rating:	<u>2.00</u>

Position	Code	Observation	Video (sec)	Grade
<b>M-707-038</b>				
.0	MGP	General Photo	10	NA
2.7	MGP	General Photo	29	NA
4.0	DSF	Deposits Settled Fine	45	M 2
5.1	IS	Infil Stain	59	NA
6.9	MGO	General Observation	74	NA




Code: **MGP**  
Description: **General Photo**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---

Code: **MGP**  
Description: **General Photo**



Distance (ft): **2.7**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---

Code: **DSF**  
Description: **Deposits Settled Fine**



Distance (ft): **4.0**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **12**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Step: **NO**  
Remarks:

---

Code: **IS**  
Description: **Infil Stain**



Distance (ft): **5.1**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:



Code: **MGO**  
Description: **General Observation**

Distance (ft): **6.9**

Structural Grade: **0**

O&M Grade: **0**

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Step: **NO**

Remarks: **Ins. Comp.**