Manhole Inspection Report



Date: 04/09/2018 Coding: Weather: **RZMACP**

M-808-011 MH#: Owner: NA Len. Surveyed: 9.2 P.O.#: John Kuglmaier 10.0 Surveyor: Rim to Invert:

> U-1215-07002349 Concrete Cert. #: Wall Material:

(reinforced)

Independence Dr. and Capitol Dr. Street:

Project: Hobart, IN Hobart, IN **GPS Northing:** 2908969.153

City: Location: GPS Easting: 2908969.153

Drain Area: Southwest GPS Accuracy: **Sub-Meter**

Cover Shape: Circular Evidence of Surcharge: No Cover Size: 23.0 Potential for Runoff: None

Comments:


Customer:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023 1

Ро	sition Code	Observation	Video (sec)	Grade
M-808-011				
.0	MGP	General Photo	10	NA
2.5	MGP	General Photo	29	NA
6.6	DSF	Deposits Settled Fine	51	M 2
7.4	MGO	General Observation	64	NA
5				
<u> </u>				
Camera Direction				
<u> </u>				
ğ				
<u>ت</u>				
*				
- 111				
- 111				
- 11				
- 11				
- 11				
- 11				
- 11				


Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MGO

Description: General Observation



Distance (ft): 7.4

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: Step:

Remarks: Ins. Comp.

NO

Wednesday, May 3, 2023