## **Manhole Inspection Report**



Date: 04/11/2018 Weather: Coding: RZMACP

MH#: M-809-025 Owner: NA Len. Surveyed: 5.7
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.2

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Intersection of Liberty St. and Murre Project: Hobart, IN

City: Hobart, IN GPS Northing: 2909629.539

Location: GPS Easting: 2909629.539

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None


Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

| Position         | Code | Observation             | Video (sec) | Grade |
|------------------|------|-------------------------|-------------|-------|
| M-809-025        |      |                         |             |       |
| .0               | MGP  | General Photo           | 10          | NA    |
| 2.5              | MGP  | General Photo           | 29          | NA    |
| 3.3              | DAZ  | Deposits Attached Other | 44          | M 2   |
| 4.7              | MGO  | General Observation     | 58          | NA    |
| Camera Direction |      |                         |             |       |

Code:



| Description:  | General Photo |
|---|---------------|
| Distance (ft): Structural Grade: O&M Grade: Clock Start/From: | .0<br>0<br>0  |
| Clock To: 1st Value: 2nd Value: Value Percent:                |               |
| Step:<br>Remarks:   | NO            |

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 3.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step:

nt: **5.000** NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 4.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023