Manhole Inspection Report



Date:

04/19/2018

Weather:

Coding: **RZMACP**

MH#:

M-907-002

Owner: NA Len. Surveyed: 11.5

P.O.#:

Surveyor:

Rim to Invert:

Customer:

Jen Costello U-907-5518 Cert. #:

Wall Material:

Concrete (reinforced)

12.7

Street: City:

On Hobart Rd. 943' South of 10th St. Project:

Hobart, IN

Hobart, IN

GPS Northing:

2909973.285

Location:

GPS Easting:

2909973.285

Drain Area: Cover Shape: Southeast

GPS Accuracy:

Sub-Meter

Cover Size:

Circular

22.5

Evidence of Surcharge: No Potential for Runoff: None

2100

Comments:

O&M Index:

Structural Index:

Overall Index:

2.00 0.00

2.00

O&M Quick:

Structural Quick: Overall Quick:

2100 O&M Rating: 0000

Structural Rating: Overall Rating:

0.00 2.00

2.00

Wednesday, May 3, 2023

1

| Position | Code | Observation | Video (sec) | Grade |
|------------------|------|---------------------|-------------|-------|
| и-907-002 | | | | |
| .0 | MGO | General Observation | 10 | NA |
| 2.1 | MGP | General Photo | 28 | NA |
| /8.0 | IW | Infil Weeper | 53 | M 2 |
| 11.5 | MGO | General Observation | 72 | NA |
| Camera Direction | | | | |



Description: General Observation

Distance (ft): .0

Structural Grade: 0

MGO

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:


Step:

NO

Code:

Remarks: ACCESS MH

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 8.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent:

Step: NO

Remarks:

2nd Value:



Code: MGO

Description: General Observation

Distance (ft): 11.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023