Manhole Inspection Report

Southeast



 Date:
 04/16/2018
 Weather:
 Coding:
 RZMACP

 MH#:
 M-910-010
 Owner:
 NA
 Len. Surveyed:
 11.3

P.O.#: Surveyor: Jen Costello Rim to Invert: 11.7
Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: NORRIS DR Project: Hobart, IN
City: Hobart, IN GPS Northing: 2911420.397
Location: GPS Easting: 2911420.397

GPS Easting: 2911420.397
GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 29.0 Potential for Runoff: None

Comments:

Drain Area:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Ouick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Р	osition	Code	Observation	Video (sec)	Grade
M-910-010					
). /)	MGO	General Observation	10	NA
	.5	MGO	General Observation	26	NA
$\sqrt{1}$	0.4	DSGV	Deposits Settled Gravel	57	M 2
1	1.3	MGO	General Observation	69	NA
Camera Direction					



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSGV**

Description: Deposits Settled Gravel

Distance (ft): 10.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code:

Description: General Observation

MGO



Distance (ft): 11.3
Structural Grade: 0

O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: Step:

Remarks: END SURVEY

NO

Wednesday, May 3, 2023 3