


Profile/Photo Observation Report



Date:	04/25/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	71.7	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-1003-002-LS025
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	9521 E Ridge Rd	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Yard	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	8"
Use:	Sanitary	Material:	PVC
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	435-2/Manhole 003 does not exist. Configuration differs from provided mapping.		
Location Details:	Grass at car wash	Direction of Survey:	Downstream
US MH:	M-1003-002	DS MH:	LS-025
		Total Length Surveyed (ft):	71.7

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	9	NA
	.0	MWL	Water Level	21	NA
	61.2	TB	Tap Break-in	211	NA
	71.7	AWW	Wet Well	323	NA



Code: **AMH**
 Description: **Manhole**

 Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **M-1003-002**



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TB
Description:	Tap Break-in
Distance (ft):	61.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AWW
Description:	Wet Well
Distance (ft):	71.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	LS-025