Profile/Photo Observation Report

2.00

Overall Quick:

Overall Index:



46.00

Date: 05/07/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): 143.5 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 SAN PSR: P-1004-024-033 Surveyor: Customer: **Red Zone** Clean Date: Shape: 2637 McAffee Dr Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Tape/Media #: Deliverable 1 Location: **Light Highway** Purpose: **Routine Assessment** Dia/Height: 16" **PVC** Use: Sanitary Material: Northeast Drain Area: Lining: NA Category: Comment: 452-2 **Location Details: Edge of street** Direction of Survey: Upstream M-1004-024 Total Length Surveyed (ft): US MH: DS MH: M-1004-033 143.5 2.00 2C00 46.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating:

2C00

Overall Rating:

.0 AMH Manhole .0 MWL Water Level 30.1 DSGV(S01) Deposits Settled Gravel 103.3 TF Tap Factory 110.9 TF Tap Factory 143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	10 37 118 204 233 323 369	NA NA NA NA NA NA NA
.0 AMH Manhole .0 MWL Water Level 30.1 DSGV(S01) Deposits Settled Gravel 103.3 TF Tap Factory 110.9 TF Tap Factory 143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	37 118 204 233 323	NA M 2 NA NA M 2
30.1 DSGV(S01) Deposits Settled Gravel 103.3 TF Tap Factory 110.9 TF Tap Factory 143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	118 204 233 323	M 2 NA NA M 2
103.3 TF Tap Factory 110.9 TF Tap Factory 143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	204 233 323	NA NA M 2
110.9 TF Tap Factory 143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	233 323	NA M 2
143.5 DSGV(F01) Deposits Settled Gravel 143.5 AMH Manhole	323	M 2
143.5 AMH Manhole		
143.5 AMH Manhole	369	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1004-033

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

10.000



Code: **DSGV**

Description: **Deposits Settled Gravel**

Distance (ft): 30.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks:

3 Thursday, May 4, 2023



Code: **TF**

Description: Tap Factory

Distance (ft): 103.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: **Tap Factory**

Distance (ft): 110.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **DSGV**

Description: Deposits Settled Gravel

Distance (ft): 143.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 143.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-024