Profile/Photo Observation Report



Date: 11/03/2022 Weather: **PACP 7.0** Coding: Pipe Length (ft): 26.0 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: YES502259 S. Bucklin PSR: P-1004-045-046 Surveyor: Customer: City of Hobart, IN (Red Clean Date: Shape: **Ryan Court** Flow Control: **Not Controlled** Street: City: Hobart, IN Year Renewed: Yard Tape/Media #: Location: Purpose: **Routine Assessment** Dia/Height: 8" Use: **Sanitary Sewage Pipe** Material: **PVC** Drain Area: Lining: None Category: NA Comment: **Location Details:** Direction of Survey: **Downstream** US MH: M-1004-046 DS MH: M-1004-045 Total Length Surveyed (ft): 18.7

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Tuesday, April 25, 2023 1

Position	Code	Observation	Video (sec)	Grade
-1004-046				
.0	AMH	Manhole	1	NA
0.	MWL	Miscellaneous Water Level	69	NA
18.7	АМН	Manhole	277	NA
-1004-045				



Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-1004-046		

Tuesday, April 25, 2023 2



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: N

Remarks:

5.000

NO



Code: AMH
Description: Manhole

Distance (ft): 18.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-045

Tuesday, April 25, 2023 3