
Profile/Photo Observation Report



Profile/Photo Observation Report							
Date: Pipe Length (ft) P.O.#: Customer:	01/14/2023 : 136.0 YES502259 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hobart S. Bucklin 10/29/2022	Coding: Pre Clean: PSR: Shape:	PACP 7.0 Heavy Cleaning P-1004-055-056 C		
Street: City: Location:	Barberry Drive Hobart, IN Easement/Right o	of Way	Flow Control: Year Renewed: Tape/Media #:	Not Controlled			
Purpose: Use:	Routine Assessme Sanitary Sewage P	ent	Dia/Height: Material:	10" PVC			
Drain Area: Category: Comment:	NA		Lining:	None			
Location Details US MH:	s: M-1004-055	DS MH:	Direction of Survey VI-1004-056	: Upstream Total Length Surveyed (ft)	: 134.4		
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00		
Structural Index:	0.00	Structural Qui	ck: 0000	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00		

Position	Code	Observation	Video (sec)	Grade
I- 1004 -056				
.0	AMH	Manhole	1	NA
0.	MWL	Miscellaneous Water Level	66	NA
17.4	TF	Tap Factory	122	NA
56.9	TF	Tap Factory	229	NA
83.5	TF	Tap Factory	309	NA
134.4	AMH	Manhole	550	NA



Code: Description:	AMH Manhole
·	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1004-056



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Continuous Index:


Within 8" of Joint:

Remarks:

5.000

NO

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 17.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:


1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

.



Code: **TF**

Description: Tap Factory

Distance (ft): 56.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 83.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: AMH Description: Manhole

Distance (ft): 134.4 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO

M-1004-055 Remarks:

5 Tuesday, April 25, 2023