

Profile/Photo Observation Report



| | | | | | |
|-------------------|-------------------|-------------|-----------------------|------------|------------------------|
| Date: | 04/25/2018 | Weather: | | Coding: | PACP 4.2 |
| Pipe Length (ft): | 132.3 | Owner: | City of Hobart | Pre Clean: | No Pre-Cleaning |
| P.O.#: | 2004 | Surveyor: | SAN | PSR: | P-703-042A-035 |
| Customer: | Red Zone | Clean Date: | | Shape: | C |

| | | | |
|-------------------|--|-----------------------------|-----------------------|
| Street: | 446 Deerpath Ct | Flow Control: | Not Controlled |
| City: | Hobart In | Year Renewed: | |
| Location: | Yard | Tape/Media #: | Deliverable 1 |
| Purpose: | Routine Assessment | Dia/Height: | 8" |
| Use: | Sanitary | Material: | PVC |
| Drain Area: | Northeast | Lining: | |
| Category: | NA | | |
| Comment: | 434-2/USMH was not shown on mapping. Configuration differs from provided mapping. | | |
| Location Details: | Edge of street | Direction of Survey: | Downstream |
| US MH: | M-703-042A | DS MH: | M-703-035 |
| | | Total Length Surveyed (ft): | 132.3 |

| | | | | | |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index: | 0.00 | O&M Quick: | 0000 | O&M Rating: | 0.00 |
| Structural Index: | 0.00 | Structural Quick: | 0000 | Structural Rating: | 0.00 |
| Overall Index: | 0.00 | Overall Quick: | 0000 | Overall Rating: | 0.00 |



| | |
|---------------------|--------------------|
| Code: | MWL |
| Description: | Water Level |
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 10.000 |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | |



| | |
|---------------------|--------------------|
| Code: | TF |
| Description: | Tap Factory |
| Distance (ft): | 52.9 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | 1 |
| Clock To: | |
| 1st Value: | 4.000 |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | |



| | |
|---------------------|------------------|
| Code: | AMH |
| Description: | Manhole |
| Distance (ft): | 132.3 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-703-035 |