Profile/Photo Observation Report

Other

Customer:

Location:



Date: 04/11/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 153.8 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Jen Costello** PSR: **P-1004-059-060**

01/01/1900

Tape/Media #:

Shape:

Street: BARBERRY DR Flow Control: Not Controlled

Clean Date:

City: Hobart, IN Year Renewed:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-1004-059 DS MH: M-1004-060 Total Length Surveyed (ft): 147.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
004-060				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
75.7	TF	Tap Factory	184	NA
75.7	MWL	Water Level	196	NA
147.9	AMH	Manhole	352	NA
11				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1004-060

AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

30.000

Code: Description: TF

NO

Tap Factory



Distance (ft): 75.7 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 75.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: AMH
Description: Manhole

Distance (ft): 147.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-059