Profile/Photo Observation Report



Profile/Prioto Observation Report								
Date:	01/08/2023	Weather:			Coding:	PACP 7.0		
Pipe Length (ft	:): 107.0	Owner:	City of Hobart		Pre Clean:	Heavy Cleaning		
P.O.#:	YES502259	Surveyor:	S. Bucklin		PSR:	P-1004-080-079		
Customer:	City of Hobart	Clean Date:	10/29/2022		Shape:	С		
Street:	Tulip Lane		Flow Control:		Not Controlled			
City:	Hobart, IN		Year Renewed:					
Location:	Easement/Right of	f Way	Tape/Media #:					
Purpose:	Routine Assessme	nt	Dia/Height:		10"			
Use:	Sanitary Sewage P	ipe	Material:		PVC			
Drain Area:			Lining:		None			
Category:	NA							
Comment:								
Location Detai	ls:		Direction of Sur	vey:	Upstream			
US MH:	M-1004-079	DS MH:	M-1004-080	Total Len	ngth Surveyed (ft)	105.6		
O&M Index:	0.00	O&M Quick:	000	00 _C	D&M Rating:	0.00		
Structural Index	0.00	Structural Q		20	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quic			Overall Rating:	0.00		

	tion Code	Observation	Video (sec)	Grade
080				
.0	AMH	Manhole	1	NA
0.	MWL	Miscellaneous Water Level	103	NA
36.2	TF	Tap Factory	227	NA
42.2	TF	Tap Factory	260	NA
96.6	TF	Tap Factory	434	NA
105.6	6 AMH	Manhole	579	NA



Code:	AMH		
Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-1004-080		



Code: MWL

Description: **Miscellaneous Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: TF

Description: **Tap Factory**

Distance (ft): 36.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value: 6.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

3 Tuesday, April 25, 2023



Code: **TF**

Description: Tap Factory

Distance (ft): 42.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:


1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 96.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 105.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: M-1004-079

NO