Profile/Photo Observation Report



Date: 04/12/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 69.7 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-1004-090-091 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Cypress Ln. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-1004-091 DS MH: M-1004-090 Total Length Surveyed (ft): 68.2

0000 0.00 0.00 O&M Rating: O&M Index: O&M Quick: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
1-1004-090				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
24.5	TF	Tap Factory	84	NA
68.2	АМН	Manhole	184	NA
1-1004-091				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-1004-090	

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:


5.000

NO

Kerriar Ks.

Code: Description: TF

Tap Factory



Distance (ft): 24.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 68.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-091