Profile/Photo Observation Report



Date: 03/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 332.9 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-203-027-034 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: E 38th Ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-203-034 DS MH: M-203-027 Total Length Surveyed (ft): 7.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
203-034				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
7.9	MSA	Abandoned Survey	49	NA
203-027				

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From:	0
Clock To: 1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint: Remarks:	NO M-203-034

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint: NO

Remarks:





Distance (ft): 7.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: no blockage