Profile/Photo Observation Report



Date: 03/28/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 341.1 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Selasie Honu PSR: P-407-011-012

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment: Flow direction wrong
Location Details: Direction of Survey: Upstream

US MH: M-407-012 DS MH: M-4074-011 Total Length Surveyed (ft): 338.8

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

		Observation	Video (sec)	Grade
4074-011				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
58.3	TF	Tap Factory	151	NA
60.1	TF	Tap Factory	169	NA
152.9	TF	Tap Factory	369	NA
187.2	MWL	Water Level	451	NA
224.4	MWL	Water Level	537	NA
239.7	TF	Tap Factory	581	NA
279.2	TF	Tap Factory	675	NA
338.8	AMH	Manhole	807	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-4074-011		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Description:

Code: TF

Tap Factory




Distance (ft): 58.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 60.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 152.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL
Description: Water Level

Distance (ft): 187.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: Water Level

Distance (ft): 224.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 239.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 279.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 338.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-407-012