Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (fi P.O.#: Customer:	04/14/2018 t): 52-1 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hoba M. Pielacha	rt	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning M-505-056-M-505-055		
Street:	Colorado Street Hobart, IN	Clean Date.	Flow Control: Year Renewed	:	Not Controlled			
Location: Purpose:	Light Highway Routine Assessment		Tape/Media #		DEP 52 18"			
Use: Drain Area:	Sanitary		Material: Lining:		VCP			
Category: Comment:	NA							
Location Detain US MH:	ils: M-505-056	DS MH:	Direction of Su M-505-055	•	Downstream Total Length Surveyed (ft):	161.6		
O&M Index:	0.00	O&M Quick:		000	O&M Rating:	0.00		
Structural Index	0.00	 Structural Qu	uick: 00	000	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quicl	c:0	000	Overall Rating:	0.00		

	Position	Code	Observation	Video (sec)	Grade
1(505)05	56				
	.0	AMH	Manhole	0	NA
	0.	MWL	Water Level	7	NA
ш	35.1	TF	Tap Factory	62	NA
	76.4	TFA	Tap Factory Active	116	NA
	122.5	TF	Tap Factory	177	NA
	161.6	AMH	Manhole	644	NA
,					



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-505-056



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 35.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 76.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 122.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

o or joint.



Code: AMH
Description: Manhole

Distance (ft): 161.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-505-055