Profile/Photo Observation Report



Date: 04/22/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 321.5 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Jen Costello PSR: P-505-067-070

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: P_C at 22 ft rocks/debris . Flow direction wrong

Location Details: Direction of Survey: **Upstream**

US MH: M-505-070 DS MH: M-505-067 Total Length Surveyed (ft): 23.9

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Rating: Structural Index: Structural Quick: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Position	Code	Observation	Video (sec)	Grade
505-067				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
23.9	MSA	Abandoned Survey	81	NA
505-070				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-505-067		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 23.9 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: unknown

NO

Tuesday, December 8, 2020